

CLASSIFIED MESSAGE

ROUTING

ORIG: [REDACTED]  
 UNIT: SSD/R&D/OSA  
 EXT: [REDACTED]  
 DATE: 15 MAY 68

SECRET

1	D/R&D/OSA	9	
2	SSD/R&D/OSA	10	
3	D/O/OSA	11	
4	OXC/O/OSA	12	
5	D/M/OSA	13	
6	D/SA	14	
7	RB/SA	15	25X1
8	D/m/OSA	16	

TO :

FROM:

CONF:

INFO:

ROUTING

CHIEF

OPS

TRANS

HOLD FOR:

TTL

INITIALS INFO

(2)

DEFERRED	X	PRIORITY	INITIALS
ROUTINE		OPERATIONAL IMMEDIATE	INITIALS

25X1

25X1

TO

SECRET

PRIORITY

INFO: PRIORITY

OXCART

REF: [REDACTED] (IN 65501)

1. REF INDICATES [REDACTED] PRINTOUT OF 68 T 075 INDICATED CAGED STATUS THROUGHOUT MISSION. THIS SEEMS TO BE SAME PROBLEM WE HAD WITH BX 6858. PLEASE ANSWER FOLLOWING:

- WAS ENTIRE 68 T 075 FLOWN IN SENSOR?
- WAS SAME SC&DM USED ON THIS MISSION AS FOR BX 6858?
- DOES DATA CHAMBER SHOW CAGED OR UNCAGED?
- WHAT IS YOUR PROGNOSIS OF PROBLEM?

2. SUGGEST [REDACTED] TYPE I PERSONNEL GO TO [REDACTED] TO STUDY 68 T 075 TO DETERMINE IF OTHER PROBLEMS INDICATED IN BX 6858 ARE APPARENT IN TYPE I-F.

3. [REDACTED] HOME PLANT IMAGERY ANALYSIS WILL STUDY O N OF BX 6858 16 OR 17 MAY 1968. END OF MESSAGE

O/OSA

OXC/O/OSA

D/M/OSA

COORDINATING OFFICERS

SSD/R&D/OSA  
 RELEASING OFFICER

SECRET

GROUP 1  
 Excluded from automatic  
 downgrading and  
 declassification

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.